

SUPERCAP TRANSMITTER

Operator Safety for Inactive Loops!

F16LSC



LOOP-POWERED DIGITAL PRESSURE GAUGE

...with Super Capacitor Backup Power!



- Display Pressure Readings if Loop is Inactive
 - Self-Recharging when Loop Power is ON
 - Recharges Fully in 2 Hours
- Maintains Charge for Months when Not in Use



User Can Operate Gauge with Loop Power Off:

- For up to 40 minutes
- @ 15-second intervals **-or-** Continuous



Suggested Applications



By Mikalantis - Wikimedia Commons



Photo by Glen Dillon

Standard Features

- ▶ **"Loop Active" LED**
- ▶ User-Selectable Engineering Units
- ▶ Scalable 4-20mADC Analog Output
- ▶ Analog Output Test Button
- ▶ Zero Tare Function
- ▶ 0.25% Accuracy

Available at
DigiKey